


houle electric limited



contractors & engineers

*the power in electrical contracting
building strength
through successful partnerships*

Date

June 11 / 09

Customer
Address

RESIDENTIAL VISUAL SAFETY INSPECTION


The following inspection was done by a certified Journeyman electrician from Houle Electric Limited .

However this inspection does not constitute a warrantee or guarantee of any kind or any liability to Houle Electric Limited.

Russ Sealey
Manager
Service Department.

RS/pjs

houle electric limited



contractors & engineers

OTHER

Battery of hard wired smoke detectors must be tested:

GOOD

Check that the kitchen outlets are on separate circuits:

GOOD

Visual Inspection of meter and Hydro connection

GOOD CONNECTION

ALUMINUM WIRING IF APPLICABLE

Check connections to duplex receptacles and switches

N/A


Check that proper devices were used:

KNOB AND TUBE WIRING IF APPLICABLE

Recommendations

N/A

houle electric limited



contractors & engineers

RESIDENTIAL VISUAL INSPECTION REPORT

CHECK THE FOLLOWING:

Ground connection to panel, water pipe and ground system if visable

Good

ELECTRICAL PANEL

Check size of main breaker 60 amps or main fused disconnect _____

BREAKERS , PANEL GOOD CONDITION
LOADING OF PANEL IS 40A DOES NOT EXCEED LIMIT WELL BELOW
GAS FURNACE AND WATER TANK

If fuses make sure they are correct size _____

NA

Check for more than one wire on breaker

NA

OTHER

GFI Breakers or GFI outlets must be checked for proper operation

Good

